

TDM Notice!

You may notice some residue on the rollers of the TDM dispenser and the cassettes. This is due to the rigorous tests that Triton performs on each unit ensuring proper functionality of our products. This residue will not affect the performance of the mechanism.

07100-00073 Rev A

TDM Notice!

You may notice some residue on the rollers of the TDM dispenser and the cassettes. This is due to the rigorous tests that Triton performs on each unit ensuring proper functionality of our products. This residue will not affect the performance of the mechanism.

07100-00073 Rev A